

L Number	Hits	Search Text	DB	Time stamp
1	2026	(315/76).ccls. (315/77).ccls. (315/82).ccls.	US-PGPUB; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:16
2	8	((315/76).ccls. (315/77).ccls. (315/82).ccls. and ((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb))	US-PGPUB; EPO; JPO; DERWENT	2004/09/30 20:58
3	1058	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb))	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:54
4	33	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and ((protect\$3 prevent\$5) near6 water)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:46
5	33	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and ((protect\$3 prevent\$5) near6 water)) not (((315/76).ccls. (315/77).ccls. (315/82).ccls. and ((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and (315/\$7).ccls.)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:36
6	75	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and (315/\$7).ccls.	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:35
7	66	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and (315/\$7).ccls.) not (5 2)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:48
8	108	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and LED\$1	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:37
9	202	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 LED\$1)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:46
10	6	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 LED\$1) and ((protect\$3 prevent\$5) near6 water)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:46
11	193	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 LED\$1)) not (8 5 2)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:55
12	141	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and (vehicle vehicular)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:55
13	117	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and (vehicle vehicular)) not (11 8 5 2)	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:58
14	813	LEDs and ((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3)) and vehicle	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 20:58
15	14	((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3) near8 (lamp tube bulb)) and (LEDs and ((detect\$3 monitor\$3 sens\$3) near6 (brok\$3 break\$3 inoperat\$3)) and vehicle ) ("6396466").PN.	USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 21:09
16	2		USPAT; US-PPG; EPO; JPO; DERWENT	2004/09/30 21:10